



Front View

Rear View




Loose/broken/delaminated
Damage/wear/hole

Previous repair
Replaced piece

Missing
Spindles not original to desk

Add-ons
Inscriptions

Right Side



Loose/broken/delaminated


Damage/wear/hole

Previous repair

Replaced piece

NOTE: No cross-banded veneer on pedestal legs

Left Side




Missing

Spindles not original to desk


Add-ons


Inscriptions


Top




← NOTE: No intwell opening!
original sides sawn


 Loose/broken/delaminated


 Damage/wear/hole


 Previous repair

 Replaced piece


 Missing

 Spindles not original to desk

 Add-ons

 Inscriptions


Bottom



■ Loose/broken/delaminated
■ Damage/wear/hole

■ Previous repair
■ Replaced piece


Bottom




■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Drawer Front, Outer Surface



Rear Surface of Drawer Front




Loose/broken/delaminated
Damage/wear/hole

Previous repair
Replaced piece


Missing
Spindles not original to desk

Add-ons
Inscriptions

Inside Surface of Left Drawer Side



Inside Surface of Right Drawer Side




■ Loose/broken/delaminated
■ Damage/wear/hole

■ Previous repair
■ Replaced piece


■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Rear Surface of Drawer Back



Front Surface of Drawer Back



■ Loose/broken/delaminated
■ Damage/wear/hole



■ Previous repair
■ Replaced piece

■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom



Possible replacement cockbeading

Loose/broken/delaminated
Damage/wear/hole


Previous repair
Replaced piece

Missing
Spindles not original to desk


Add-ons
Inscriptions

Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side



↑ *Rabbetted drawer front* →



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Missing

Spindles not original to desk

Add-ons

Inscriptions